

Site Name/Location: Cabo Rojo Groundwater Contamination Site, Cabo Rojo Puerto Rico

**DATE:** 4/17/13 **WEATHER:** 98 Degrees F, Sunny and rainy in the afternoon

PERSONNEL ONSITE

#### **CDM Smith**

Frances Delano Patrick Connelly José Reyes

## **CDM Subcontractor**

Joel Alvarado, driller Luis F. Santiago, driller Orlando Marrero, driller

**FIELD EVENT:** Continue sampling soil vapor

#### FIELD WORK PERFORMED:

Equipment was calibrated and checked

- Field GC Screening results for Unfinished Strip Mall:
  - US-SV-02 / 5 5.5 ft bgs PCE .210 ppm [PID readings: CO 11.0/ VOCs 0.0]
  - US-SV-03R / 6-6.5 ft bgs ND
- Field GC Screening results for Raul Lugo Storage Yard (Complete)
  - RL-SV-01 /7.5-8 ft bgs- PCE 0.134 [PID readings: CO 5/ VOCs 1.3]
  - RL-SV-02 /4-4.6 ft bgs ND [PID readings: CO 727/ VOCs 2.2]
  - RL-SV-03 / 7.5-8 ft bgs PCE 0.133 / DCE 0.147 [PID readings: CO 42/ VOCs 2.9]
  - RL-SV-04 / 7.5-8 ft bgs PCE 0.127 / DCE 3.035 [PID readings: CO 466/ VOCs 2.1]
  - RL-SV-05 /7.5-8 ft bgs PCE 0.122 / DCE 2.372 [PID readings: CO 225/ VOCs 2.5]
  - RL-SV-06 /1-1.5 ft bgs PCE 0.187 / DCE 5.069 [PID readings: CO 287/ VOCs 9.8]
  - RL-SV-26 /1-1.5 ft bgs PCE 0.207 / DCE 4.723 (Duplicate of 6)
  - RL-SV-07 /7.5-8 ft bgs ND [PID readings: CO 473/ VOCs 2.6]
- Confirmatory Sample collected:
  - RL-SV-03C
- Sampled Confirmatory samples sent to lab (2 Summa canisters including used hardware)
- Reanalyzed samples collected yesterday
- Had a meeting with drilling crew for tomorrows plans
- Checked equipment to corroborate that they have everything to start the soil and groundwater sampling.
- Jun Portable arrived to the site to retrieve portable potty
- Health and Safety meeting
- Security arrived to site

# Proposed next day event:

Start sampling soil and groundwater screening at Cabo Rojo Dry Cleaners

## Proposed next days/week schedule:

- Apr.19/2013 Complete sampling soil and groundwater at Cabo Rojo Dry Cleaners
- Apr.22/2013 Start soil vapor sampling at PRIDCO west (Propper International, active)
- Apr. 23/2013 Complete soil vapor sampling at PRIDCO west (Propper International, inactive)



Site Name/Location: Cabo Rojo Groundwater Contamination Site, Cabo Rojo Puerto Rico

- Apr. 24/2013 Start /complete sampling at SerranoII Dry Cleaners
- Apr. 25/2013 Start/complete sampling at Walgreens
- Apr.26/2013 Possibly short day to compensate for extended sampling day at Walgreens and if needed finish sampling at Serrano II

## **MISCELLANEOUS:**

- Collected a control sample at the Unfinish Strip Mall to compare the results of the sample collected yesterday that was reanalyzed today to a sample collected and analyzed on the same day. The response was similar but PCE was detected in the sample collected yesterday and for the one collected today there were no contaminants of concern detected.
- Madeline Asencio property owner of the Cabo Rojo Dry Cleaners called to inquire about the sampling inside the building. We explained to her that all sampling locations will be abandoned on a daily basis and that no instrumentation will be installed (left behind) at this phase. She understood but was uneasy about when we will have results of this investigation.
- Sampling at WR Recycling has not been added to the schedule but the corresponding Summa canister will be hold until further notice.
- Called A-1 to verify the delivery of the portable potty
- We have experienced delays in the analysis of samples since we have to wait about 10 minutes between samples so that the peaks are not influenced between consecutive samples. As such Patrick Connelly would have to complete the samples from yesterday as well as the samples collected today.